BAL HARBOUR

- VILLAGE -

Reinaldo Borges, Chair Elizabeth Camargo, Board Member Jose L. Gomez, Board Member Nathan VanDeman, Board Member David Koplowitz, Board Member Village Manager Jorge M. Gonzalez Village Clerk Dwight S. Danie Building Director Eliezer Palacio Village Attorneys Weiss Serota Helfman Cole & Bierman, PA

ARCHITECTURAL REVIEW BOARD

SUPPLEMENTAL MEETING AGENDA JUNE 21, 2024 AT 1:00 P.M.

Bal Harbour Village Hall • 655 - 96th Street • Bal Harbour • Florida 33154

This meeting will be conducted in-person. The meeting will also be broadcast on the Village's website (www.balharbourfl.gov) and members of the public are encouraged to participate by calling 305-865-6449 by emailing meetings@balharbourfl.gov before and during the meeting.

SUPPLEMENTAL CONSENT AGENDA

4.6 ARB-2024-0011

9601 Collins Avenue, Bal Harbour FL, 33154

Architect(s): Ken Gardner

Owners: Majestic Tower Community Association, Inc.

Landscape renovation to pool area / plantings, hardscape and cabana fronts.

1- 9601_Collins_Ave - ARB2024-0011 - ARB MEMO (FINAL).pdf

2-9601 COLLINS AVE - ARB2024-0011 - POWERPOINT -FINAL.pptx

3-9601 COLLINS AVE - ARB2024-0011 - APPLICATION.pdf

4- 9601 COLLINS AVE - ARB2024-0011 - NARRATIVE.pdf

5-9601 COLLINS AVE - ARB2024-0011 - PROPERTY APPRAISER.pdf

9601 COLLINS AVE - ARB2024-0011 - ORIGINAL MEMO (2021).pdf

One or more members of any Village Committee/Board may attend this meeting of the Council and may discuss matters which may later come before their respective Boards/Committees. The New Business and Council Discussion Section includes a section for Public Comment. On public comment matters, any person is entitled to be heard by this Council on any matter; however, no action shall be taken by the Council on a matter of public comment, unless the item is specifically listed on the agenda, or is added to the agenda by Council action. Any person who acts as a lobbyist, pursuant to Village Code Section 2-301 (Lobbyists), must register with the Village Clerk, prior to engaging in lobbying activities before Village staff, boards, committees, and/or the Village Council. A copy of the Ordinance is available in the Village Clerk's Office at Village Hall. If a person decides to appeal any decision made by the Village Council with respect to any matter considered at a meeting or hearing, that person will need a record of the proceedings and, for such purpose, may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based (F.S. 286.0105). In accordance with the Americans with Disabilities Act of 1990, all persons who are disabled and who need special accommodations to participate in this proceeding because of that disability should contact the Village Clerk's Office (305-866-4633), not later than two business days prior to such proceeding. All Village Council meeting attendees, including Village staff and consultants, are subjecto security screening utilizing a metal detector and/or wand, prior to entering the Council Chamber, Conference Room, or other meeting area located within Village Hall. This is for the safety of everyone. Thanks for your cooperation.



ARCHITECTURAL REVIEW BOARD MEMORANDUM

TO: Architectural Review Board Members

FROM: Eliezer Palacio, Building Director

DATE: 6/21/2024

SUBJECT: 9601 Collins Avenue

(Revision of ARB-21-05-001) Landscape renovation of an

existing multifamily condominium

BACKGROUND

The Village of Bal Harbour the "Village" received an Architectural Review Board (ARB) application on April 05, 2024 for the Landscape renovation of an existing multifamily condominium located at <u>9601 Collins Avenue</u> ("the Property").

The Property sits on Lots 1, <u>Majestic Tower at Bal Harbour</u> and is located in the Ocean Front zoning district of the Bal Harbour Village.

THE PROJECT (AE Description)

This project consists of a landscape renovation of an existing multi-family condominium.

The existing Pool and Spa are to remain. The pool deck materials will be changed out to light gray stone pavers, the plantings will be replaced and enhanced with new salt and wind tolerant materials. At the building's restaurant the existing outdoor dining space will be enhanced with a pergola and at-grade deck with plantings around it. The existing cabanas will have wood panels applied to the exterior face, and new lighting. The current metal picket pool fence replaced with a wood and stone fence and an enhanced entry structure.

This is a revision to the previously approved landscape plans by ARB in 2021. This does not represent a material deviation from the approved plans.

These plans have been revised, because the Condominium association has decided to maintain the Pool and Spa in the exact locations and shapes, just providing new finishes. The Association wanted to simplify the design, and the Landscape Architect has been changed.

(Original AE Description for ARB-21-05-001) The project consists of a landscape renovation of an existing multifamily condominium. Portions of the property (the north podium and east beach area) are outside of the limits of landscape renovation; however, the applicant will add a prefabricated playground structure accessible to residents of the Majestic Tower only on this mezzanine level.

For the west portion of the property along Collins Ave, the landscape canopy trees will be selectively thinned to remove trees that are overgrown or in poor condition, and trees will either relocated or replaced to bring a fresh design vision to the property. The understory planting materials will also be replaced with new materials consistent with the character of Bal Harbour and suitable for the conditions of the site.

Both driveways (Collins and 96th) and the residence entrance drop-off will have new paving materials proposed, bringing the palette in harmony with the architectural fa?ade and proposing a similar scallop pattern to the existing driveway while working within the existing conditions of the planter walls.

An opening is proposed in these walls at three locations to be able to provide for pedestrian access to an underutilized portion of the landscape and transform this space into a tranquil garden park.

The pool deck on the east portion of the property will undergo renovation to change the shape of the pool to a more contemporary shape with clean lines while staying within the existing pool shell's structural footprint. The spa will also be redesigned with the same clean lines while utilizing the existing piles. The pool deck materials will be changed out to a light gray stone paver, the plantings will be replaced and enhanced with new salt and wind tolerant materials. At the building's restaurant, the existing outdoor dining space will be enhanced with a pergola and at-grade deck with plantings around it. The pool deck space is proposed to be unified with a wraparound trellis extension at the existing cabanas, and the current metal picket pool fence replaced with a glass panel fence with greater visibility towards the beach.

RECOMMENDATION

It is the opinion of this writer that the proposed project and restoration of the existing multifamily condominium follows the Village's Appearance Code and Zoning Ordinance. The Village Planning and Zoning Consultant and the Park's and Public Spaces Department has reviewed the plans and concur that the plans comply.

I recommend that the Board review the submittal for compliance and if they concur with my recommendation, issue a Certificate of Appropriateness.

If approved, the following conditions should be added to the motion:

- 1. Landscape Architect shall provide certified letter demonstrating compliance with Miami-Dade County Chapter 18A.
- 2. Trees shall be added to meet or exceed the previously approved tree canopy prior to issuance of a Certificate of Occupancy.
- 3. Compliance with Village Code of Ordinances Section 20-29, regarding obstruction of water meters, and Section 21-358 regarding walls, fences and landscape plantings.
- 4. A construction contract and or detailed estimate of the proposed improvements is required to be submitted to establish proposed construction value.
- 5. Zoning and Flood Resistant Design Review information included in this approval and backup report consists only of a preliminary review against the basic intent of the Village's Zoning Code and F.B.C. Chapter 16 requirements. Complete review and compliance with the Village Zoning Code and the F.B.C. shall be required prior to permit approval.
- 6. Applicant to apply for and obtain all required permits from the Building Department before beginning work.
- 7. Applicant to apply for and obtain all necessary permits and approvals from outside agencies.
- 8. Pursuant to Village Code 2-75(d)(1-3), the Certificate of Appropriateness expires 18 months after issuance, if a principal building permit is not obtained to develop the property in accordance with the Certificate of Appropriateness.

Sheet Cover




Sheet Site Location

majestic tower | site reference | site location







Sheet T-00
























Sheet G-01






Sheet A-80





Sheet 3D-Q





Sheet 3D-001,







1)3D VIEW @ POOL AREA

②3D VIEW @ POOL AREA



3 3D VIEW @ POOL AREA



(4)3D VIEW @ POOL AREA



5 3D VIEW @ POOL AREA



ARCHITECT'S WRITTEN SPECIFICATIONS ACCOMPANY DRAWINGS & ARC A PART OF THESE CONTRACT DOCUMENTS ENGINEERS SPECIFICATIONS ARE INCLUDED ON DRAWINGS.

9601 COLLINS AVE
BAL HARBOUR, FL 33154


DEMANS HIS PLOCK NUMBER
PROPOSE POOL & CARANAS AREA
30 HENDERNOS
JOHANS IS SHEET BIS.

21911

3D-001



Sheet 3D-0





Sheet 3D-003.00







3D VIEW @ FRONT DRIVEWAY





3 3D VIEW @ FRONT DRIVEWAY



(4)3D VIEW @ FRONT DRIVEWAY



5 3D VIEW @ FRONT DRIVEWAY




MAJESTIC TOWER 9801 COLLINS AVE BAL HARBOUR, FL 33154 SETTLE PLOCH NUMBER PROPOSE ARBEVAL AREA 3D HENDERINGS

21911 3D-003.00



Sheet Survey





SURVEYOR'S NOTES:

- Bearings hereon are referred to an assumed value of N 8552'35" E for the North right of key Average, and economical by two (2) set. 1/2" alpee d. cape (USS653).
- Elevations since Torsion are relative to the Netbert Depositio Vertical Datum of 1925 Borich Nork No. 2-313, Edvation 10.50, located at Colleg Assistance and 98th Street.

- This may is intended to be distinct at the anothic socie shows never or smaller

- Fursions to Eurise State Statutes in Creater 167.161, it designates that an uptord property to owned of the edical dead Position Control Line shall rampin the property of the uplant owner.
- Folio No. 12-2225-035-0001 (Reference Folio No.) per Miem-Code Property Appropria with site

SURVEYOR'S CERTIFICATION:



SURVEY RBOUR BOUNDARY & TOPOGRAPHIC THE MAJESTIC TOWER BAL HAR BAL HARBOR VILLAGE, MAMI-DADE COUNTY,

1" = 20" 980622 'ted Plotted 4/20/24 9:50a Ref. Deg. 296D-239 Yeld Book 497/25 & 1 SD ob No. 201008 Dwg. No.

INC. KILES, I EYORS & MAI

MAJESTIC TOWER

Sheet Survey page 2










	EXISTING TREE I	JISPOSITION	LIGI	- I KE	ES WI	Time O	COLF	01 11	OIGI
EY	BOTANICAL NAME	COMMON NAME	HT.IH 1	SED. (F: 1	DBH.(in.)	REMAIN	SEMOVE III	RANSPI	MITIGATION S.F. CANOPY
4490	Livistona chinessia	Chinese Fan Folm	14	10	10	moult	3		70
		Chinese Fan Polan	14	10	10		X		79
	Cocca mocifies Lucatron changesia	Coconut Palm Chinese Fan Folm	35	10	10		3	_	113
6494	Livatono disnessis Livatono disnessis		14	10	10		x		79
4495	Livistono drinensis	Chinase Fan Polari	14	10	10		х		79
	Cocos revaless Uvietorio dri nensis		35	12	10		X		113
6697	Livistono divinensis	Chinase Fan Poles Chinase Fan Poles Chinase Fan Poles	14	10	10		X	_	79
6499	Livetono di nersia Livetono di nersia	Chinese Fan Polin	14	10	10		X		79
	Livistono drinensis Phoenix dactylides "Medjool"	Chinese Fan Polm Medyool Date Pelm	14:	10			X		.79
6579	Phoenix dactyldes "Medjool"	Medyool Date Palm	35	20	14	X	_		
4580	Fhoenix dactylrlers "Medjool" Phoenix dactylrlers "Medjool" Fhoenix dactylrlers "Medjool"	Medjool Date Palm Medjool Date Palm Medjool Date Palm	35	20	14	X	\rightarrow	\rightarrow	
4582	Phoenix dachlines "Medjool"	Medical Date Palm	35	20	14	×			
	Phoenix dactylinas "Medjool"	Medjool Date Palm	35 10	20	14	X			
6511	Phoenix dachfridaa "Medjool" Phoenix dachfridaa "Medjool" Phoenix seebelenii Coose mudikes	Medical Date Palm Pygery Date Palm Coconut Falm	10	12	10		X	_	50 113
6512	Barebas rulgars rittata	Coldan Haveilan Barebo	35	12	nuh nuh	×	X	-	113
			25	20		X			
	Cooss musikes Uvistono chinerais Phoenis rodelenii	Coccount Polini Chinase Fan Polini	35 12	12	10		X		113
6516	Liviatono chi neraia	Chinase Fan Polan	10	10.	10		X	-	50
6518	Livinium dimensis	Pygany Dote Poles Chinese Feta Poles	16	1	6		3	-	50
6519	Evatora di nessis Evatora di nessis	Chinese Fan Poles Chinese Fan Poles	20	8	ó		X		50
4520	Livatorio chi neraia Livatorio chi neraia	Chinese Fan Poles Chinese Fan Poles	20 12	4	ó		Х		50
6522	Livatono chineraia	Chinese Fan Poles	12	8	ó		X		50
6623	Liviationo disnersis Liviatono disnersis	Chinese Fan Poles	12	8	6		X	-	50 50
4626	Livetone drineres	Chinax Fan Folm Chinax Fan Folm	18	ė	6		â	-	50
6632	Livatona drinerea Livatona drinerea	Chinese Fan Polm Chinese Fan Polm	0	8	6		X		50
	Livatono di nessa	Chinese Fors Polan	20	8	6		X		50
4635	Evelona drinerala Livelona drinerale		22	5	6		X		50
4537	Equityres resp	Chinese Fan Polen Board Polen	25	15	12		Ŷ	-	177
6538	Cocce mucikes	Coconut Palm	35	12	10		X		113
6638A	Uvationa difininsia Uvationa di mensia Populorien regio Cocca mudikra Ugustrum japonicum Cocca mudikra	Royal Polin Coconut Ralim Was-last Privat	10	10.	muhi 10			X	
4639	Cocos nucifero		35	12	10		X	ΨŢ	113
	Ligaritan japonicim	Wax-loof Privat	10	10	endi multi			X	
6540	Phoenic robellars		18	6	4		X	^	28
	Phoenix robellins Phoenix robellins Phoenix robellins	Pygwy Dote Polin	12	15	3 mels		x		127 113
4544	Physicia robell es		12	12:	3 hunks		X		113
	labelsuia natiobea Livistosia chinensia	Silver Transpet Texas Chinese Fan Poles	16	25 12	12		X	_	491 113
			18	12	8		2	-	113
4650	Satebula cariotea Tatebula cariotea	Silver Trampet Tree Silver Trampet Tice	16	1	8		3.		50 79
4653	Tabebula cartoboa	Silver Trampet Tree	16	10	8		3.		79
4655	Tabebulo cariolies Livistono chinensis	Silver Trumpet Tree Chinese Fan Polm	18	25 12	12		X	_	491 113
4607	Livistona disnessis	Chinese Fan Form	20	12	8		A.	_	113
4562	Livatono di nessa Livatono di nessa	Chinese Fan Poles Chinese Fan Poles Chinese Fan Poles Stiver Trampet Tice Method Date Poles Chinese Fan Poles Chinese Fan Poles	20 20 16	12	5		3	\rightarrow	113
		Silver Trampit Time.	16.	10	8		- 3		
	Phoenix dachklera "Medjool" Livatona drinavia Livatona drinavia	Medjool Date Polm	35	20	14		X		314
4500	Livistono drinerais	Chinese Fan Poles	20	12	7	_	- 3	-	113
4477	Licology designs	Chinese Fan Polm	20		2	-	X .	\rightarrow	
4574	Livatono chimenata Livatono chimenata	Chinese Fan Polar Chinese Fan Polar	20	12	7		X		113
4575	Liviaciono chi mensis.	Chinese Fan Polan Chinese Fan Polan	20	12	7		X		113
4576	Livetono di nensis Livetono di nensis	Chinese Fan Polan Chinese Fan Polan	20	12	7		X	_	113
6670	Liverone damente	Chinese Fan Polin	50	12	7	-	X Y	-	113
455D	Livatono di nersis Livatono di nessis		20	12	7		x	_	113
4681	Phonocoodins Livetono chinessa	Pygery Date Pales Chinese Fan Pales	12		2 mode		.3.		50 113
		Chinese Fan Polin	20	12	7.		X		113
4683	Livatono dri sensis	Chinese Fan Folan	20	12	7		. X	_	113
6586	Livatono dimensia Phoenix sobellini Livatono chinensia	Chinese Fan Rola: Pygany Dole Rula: Chinese Fan Polei	20	12	7		X		13 113
4588	Phoenic roboth in	Pygwy Dote Poles	12	12	3 works		X		113
	Phoenix spellins Phoenix spellins Phoenix spellins	Pygany Dote Poles Pygany Dote Poles Pygany Dote Poles	8	6	0.		X		28
4591	Phoenix robellins	Pygany Dote Poles	8	6	0		X		28
	Phoenix robelites	Pygwy Doto Poles Chinese Fan Poles	50	12	6		X	\rightarrow	26 113
4594	Phoenix sobellini Uvenong chinensa Phoenix dachlirlera "Medposi"			15	14		3	_	254
4695	Phoenix dacty/riea "Niedjool"	Medjool Date Pelm	35	18	14		X		254 254
			35	18:	14		X		254
6597	Phoenix doctyldes "Medjool" Phoenix doctyldes "Medjool" Phoenix doctyldes "Medjool"	Medjool Date Palm Medjool Date Palm Medjool Date Palm Medjool Date Palm	35	18:	14		X		254 254
4599	Phoenix dactylnes "Nedool"	Medical Date Palm	35	18			X	_	254
1700	Phoenix dactyli lea "Medjool" Phoenix dactyli lea "Medjool"	Medjool Date Palin Medjool Date Palin Medjool Date Palin Medjool Date Palin Medjool Date Palin Medjool Date Palin Medjool Date Palin	35	18	14		Х		254 254
	Phoenic da: Nillea "Medioci"	Medjool Date Palm	35	1.5	14		X		254
	Phaesix dact/likea "Medjool" Phaesix dact/likea "Medjool"	Madjool Date Palm	35	18	14		X		254 254
1701	Phoenix doctyldes "Medicol"	Medical Date False	25	18			X X	_	254
4705	Phoenix dachlifea "Medicol" Hisenix dachlifea "Medicol" Phoenix dachlifea "Medicol"	Medjool Date Palm Medjool Date Palm	35	18	14		X		254 254 254
	Phoenix doctyldera "Medjool"	Medjool Date Palm	35	18	14		3.		254
1707	Phoenix dacyklera "Medjool" Phoenix robellini	Medical Date Palm Pygwy Date Palm	35.	15	14 3 mels		X		254
		Progray Date Pales	14	16.	3 mode		X		201
6711	Phoenix robell in Phoenix robell in	Pygwy Dote Holes Pygwy Dote Poles	8	10	3 trunks. 2 trunks		X		79
	Phoenix robellini		8.	12	3 montes		X		
1713	Phoenix reditato	Senegal Date Pales Silver Transport Teas Medipoli Date Pales	30	23	8 huels			X	254
6714	Tabeluria carletina Phraesia diachili fina "Medjool" Esmarckia nobelis	Monte Transport Team		18	14		X		
1717	Firena nacyces Welloof	Wedpool Date Felm Bismarck Palm	35 25	12	12		X	_	254 113
4761	Cocos roceletz			18			X	_	254
	Cocos muciles: Cocos muciles:		40	15	10		X		254
	Coos nuclius Coos nuclius Hysphodu vershafulis Hysphodu vershafulis Hysphodu vershafulis	Coconst Palm Coconst Palm Skindle Palm Spindle Palm Spindle Palm	32	16.	10		X		201
	Physotode verehofelti	Spindle Poins	10	2	ň		3	-	26
	Hysphodu reschafelti	Spendla Palm	11	8	10		X		50
			6	10	10		X		
	Hysphodie verschoffelts	Spindle Fairs	0	0	12		X		50
	Myaphode reschafels Myaphode reschafels Hyaphode reschafels	Spindle Pains Spindle Pains Spindle Pains	13	10	12 10 10		3.		50 79
4771	Hysphoide verschoffelts Cooss nuclers	Spredle Palm Coccout Palm	30	14	9	-	X	-	79 154
4773	Cocos rescieno		26	14	9	-	Ŷ	-	154
4774	Cocos nucleiro Myophodin recotad/witi Cocos nucleiro	Spindle Palm Coconut Palm	5	6	12		х		26
4775	Cooss nucriero	Coconut Falm	26	14	8		X		154
		Coconut False	26	16	9		X		154
5150	Cocca nuclies var. "Gram Malayan" Cocca nuclies var. "Gram Halayan"	Coconut	30	15	8		3		177
5160	Coxes rocikes vor. 'Cress Halovan'	Goconat	30	15	8		X	_	122
	Cocca nocifica vor. "Grass Maloyon" Cocca nocifica vor. "Grass Maloyon"		30	15	8		Х		177
	Phoenix robellini Phoenix robellini	Pygwy Dose Pales Pygwy Dose Pales					X		0
		grygwy Dioto Polen	_	_	_		X	_	
5165	Phoenix robellini	Pygyry Dote Pole:							

MITIGATION TYPE	QTY.	MITIGATION FA. (S.F.)	TOTAL MITIGATION (S.F.)
Shople Tear I	5	500	2500
Shade Tire 2	32	300	9600
Polm Tipe 1	7	360	2/00
Polin Tee 2	0	100	0
Small Time	0	200	D
GRAND TO	TALSE, MITIGATION CA	NOPY PROVIDED*	14200





TREE PROTECTION DETAIL

TREE & PALM TRANSPLANTING NOTES:

- Prior to root pruning and before excavating holes for transplanted trees, check with all local utilities to locate existing underground utilities. If any unknown utilities or sprinkler piese are in advertently boken, do gate cover them up. Immediately notify the utility and/or the Client, and take all necessary steps to repair the break.
- 2. Root prune frees a minimum of 8 weeks prior to moving them. It is not necessary to not prune pilans prior to transplatting unless specifically instructed to do so by the Landscape Architect. Proto to not pruning thomoughly water these or once with at least 2°-3° of water. Root pruning shall be accomplished by digging a trends tro-dunisk (2°)'s of the way around the next at animism of 2° deep. Root prune qu'y with a mechinary new or it trends or with a maximum treach while of 8 nackes. This trench shall form a rowelled of the minimum following sixes.

Up to 5* caliper 3' diameter 6"-8" caliper 4' diameter 9"-12" caliper 6' diameter Over 12" caliper 8'-10' diameter

- The amount of general pruning and thinning of the leaf mass shall be limited to 1/3 of the tree canopy or only the fronds that are more than 50% dead, unless otherwise directed by the Landscape Architect.
- 3. Plant holes shall be roughly cylindrical in shape with sides approximately vertical. The depth of the hole shall be equal to the roofball depth plus 12" unless further depth is required to provide adequate derinage. The diameter of the hole shall be a minimum of 24" larger than the rootball diameter.
- 24" lager than the rookal diameter.

 4 "HANN MATRIAL SHALL BE PLANTED AT THEIR NATURAL AND ORGIGAL PLANTING IEVEL PRIOR TO THEIR PLACEMINT ON THIS AT PROJECT OF JOIN, WHEN LOWESTED THAT THE PLANTS SHELD STATE OF THE PLANTS SHELD S
- Backfill the bottom two-thirds of the planting hole and firmly tamp and settle by watering as backfilling progresses. After having tamped and settled the bottom two-



his displays a fire property of CNIA Dasign one is not to be reproduced on copied in white or part effects without matter than a matter or part effects where the property of the international property of the property of th


MAJESTIC TOWER 9601 Collins Avenue Bal Herbour, FL



05.03.2024 as noted

LA.2







Sheet LA.4





TREES	T LOS	IT LIST		
KEE2	PLANT NAME	QTY.	LIT	Isize
KEY BUSI	Busens singuistic	2	eG.	14' toll x S' spread, 3' DBH , 4
	Gumbo Limbo	1	00.	CT min.
CHSP	Chorisia speciosa	1	eg.	16' tall x 6' spread, 4' DBH
	Silk Ploss			
1000	Coccoloba diversilolia	20	œ.	12' toll x 5' spread, 2' DBH), 4
	Pigeon Plum			CT min.
COER	Conocarpus arectus	5	œ.	18' tall x 8' spread, 4' DBH
	Green Suttenwood		-	
LUA	Ligoshum japonicam	4	60.	16' lall x 6' spread, multi,
MYER	Ligustrum Microanthos fragrans	8	-	specimen 12' toll x 5'-6' spread, 3 trunks
MICH	Simpson's Stopper	9	60.	When to tree form
QUVI	Ovorces virginiana	2	og.	12 toll x 5' sproad, 2' DBH, 4'
	Live Oak		uu.	CT min.
PALMS				
	PLANT NAME	QTY.	Tur.	SIZE
BINO	Bismarckia nobilis	7	60.	18' toll CA
	Bismarck Palm			
DYCA	Dypeis cabadae	1	60.	12' toll OA, multi-trunk
	Cabada Palm			
ELOL	Elonis olaifero	2	60.	18' toll OA
200	"American Oil Palm	3	-	12 toll CA
MYLA	Hyophorbe loganiosulis	3	00.	12' toll OA
JRO	Bottle Palm Uvistana rotundifalia	11	eg.	12 toll OA
500	Livistona ratunditalia Foat Stool Palm	111	ec.	TE FOR CH
PHDM	Phoenix dactylifera Medjool	10	en.	25' OA HT. Matched
- name	Medjool Date Palm	100	1	10.000.000.000
THRA	Thrings radiata	9	00.	6' toll CA
ВАМВО	DO & OTHERS			
KEY	DO & OTHERS PLANT NAME	QTY.	Tur.	SIZE
UNAS	Bambasa multiplax	5	œ.	18' toll overall, 6-7 culms per
	Hedge Bamboo		1	dump
SHRUB	\$			
KEY	PLANT NAME	QTY.	UT.	SIZE
BOAR	Borrichia arborescens	36	eo.	24" x 24", install 24" a.c.
	Silver Oxogo Dalay			
MORE	Portea petropolitana	7	œ.	5 tall x 3 spread, full to group
	Bromeliad Porten Jungle			
CANA	California americana	21	60.	30" x 30", install, 24" a.c.
	Arrerican Beautyberry			
CACY	Capparis cynophallophoss	239	ec.	24'x18', full
	Jamaica Caper			
CHIC	Chrysobolanus icaco	316	ec.	18" x 16", install 18" a.c.
oora:	"Coceplum	10	-	0.07.00.16
COE32	Conocorpus erectus	12	90.	5-6 Tall Shrub Form
00111	Green Buttonwood	a.	-	
DRMA	Dracaona marginata "Dragon Tece"	26	00.	4-5 tall overall, 2-3 ppp
rigi	Dragon Tros Ficus microcarpa "Green Island"	142	1	18'x18', install 24" o.c.
101	Frous microcarpa "Green Island" "Ficus Green Island	142	00.	18'x18", install 24" o.c.
11000		3.40		0.1
MUCA	Muhlenberghio copillors	140	60.	3 gal cans, full
	Muhly Grass	49	-	
PSNE	Psychotria narvosa Wid Coffee	49	00.	18'x18"
21150		41		10/10/
RUBR	Ruellia brittoriana Mesican Blue Bell	81	eg.	18'x18', install 24' o.c.
SERE		32	80	24" x 24", install 24" o.c.
SEKÉ	Seneroo repens	32	90.	24" x 24", mstall 24" o.c.
TEDA	Sow Palmetto	168	-	3 gal cans, full, install 36" o.c.
AUA	Tripsocum doctyloidos Fokahatchee Gross	168	oc.	a gar care, full, install 35° o.c.
			_	
	NDCOVERS	1	-	
ARGL	Arachis glabrota	1530	60.	1 gal cans, full, install 9" a.c.
CRU	Perennial Peanut Ernodea Littoralis	77	00.	
CKU	Califor Course	177	00.	3 gal cans, full, install 24" o.c
JEG	Golden Creeper Unicpe muscari Evergreen Glant	1891	60.	1 gallon cars, full, install 12*
	Forester Gird British	IOV	ec.	n gamm cans, nat, makali 12"
AWA	Evergreen Giord briope Pilea microcarpo	837	60,	8' x 8', install 12' o.c.
-	-Artiflery Forn	100	1	,
		_	_	
MISCE	LIANEOUS	-	-	
	Planting Soil: 70% Silica Sand	as req.	C.7.	oscavate and backfill 18" dept
	20% Silica Sand 20% Everalades Muck			in all planting areas.
	20% Everglades Muck 10% Shredded Ptrebank			
		-		
	Artificial Sod St. Augustine 'Chrobine'	as req.	8.5.	see interior design plans
	of, Augustine 'Citrobiue'	as req.	5.5.	solid sod 3' layer in all shrub beds
			C. V.	par sover in all shrub bads
	Shifted Dod. Mellaneuca Mulich			
	Shredded Melaleuca Mulch Rootguard	os req.	I.E.	24" deep, manufacturer to be
	Rootguard	as seq.	I.E.	24" deep, manufacturer to be selected
	Shifted Dod. Mellaneuca Mulich		LE.	24° deep, manufacturer to be selected install 3° deep over landscape
	Rootguard	as seq.	I.E.	24" deep, manufacturer to be selected install 3" deep over landscape fabric, decorative gravel to be
	Rootguard	as seq.	t.f.	24' deep, manufacturer to be selected install 3' deep over landscape


Zor	ing District: OF Net Lot Area: 1.15 (acres) 50,211 (square	feet)	
OP	EN SPACE REQUIREMENTS	REQUIRED	PROVIDED
۸.	Square feet of open space required by Chapter 33, as indicated on site plan: Net Lot asso = 50,211 square feet x 25 % = 12,553 square feet	12,553	15,339
В.	Square heet of parking fot open space required by Chapter 18A, as indicated on site plan: The number of parking spaces 12 k 10 square feet per parking space —	120	120
C.	Total square feet of landscaped open space required by Chapter 33 = A+8=	12,673	15,459
LAV	YN AREA CALCULATION	MAXIMUM	PROVIDED
Α.	Total square first of landscape open space required by Chapter 33 =	12,673	
В.	Maximum laws ama (Non-Bahia sod) permitted = 60 % = 7,604 square feet =	7,604	325
TRE	ES	REQUIRED	PROVIDED
	SITE TREES		
Α.	The number of fees required per net lot acre. = 28 tross a net lot acroage = TOTAL SITE TREES	33	40
	less the existing number of trees that meet the minimum requirements	-	
	TOTAL NEW SITE TREES	33	40
	STREET TREES	-	
8.	Street trees [max. average spacing of 35" o.c.]: 400 linear feet along street / 35 =	12	12
	Street trees located directly beneath power lines (Max. average spacing 25 o.c.): No. Illinear feet along street / 25		-
	Polins as street trees (max. average spacing of 25' o.c.) 10/0 linear feet along street / 25 =		
	TOTAL STREET TREES	12	12
	GRAND TOTAL TREES REQUIRED	45	
C.	30% palm spacies allowed (two palms = one tree) Palms provided =	12	10
D.	Percentage of native tress required = number of trees provided x 30% =	14	37
	RUBS	REQUIRED	PROVIDED
A.	The total number of trees required x 10 - the number of shrubs required	450	
	The total number of shrubs required x 30% = the number of notive shrubs required	135	1013













MAJESTIC TOWER

Bal Harbour, Florida

9601 COLLINS AVENUE BAL HARBOUR, FLORIDA 33154

MAJESTIC TOWERS - SHEET INDEX

SHEET#	SHEET NAME	SUBMISSION 05/12/2021	
L-000	COVER SHEET	X	
L-001	SITE IMAGES	x	
L-100	TREE DISPOSITION PLAN	x	
L-101	TREE DISPOSITION PLAN	x	
L-102	TREE DISPOSITION PLAN	x	
L-200	SITE PLAN RENDERING	x	
L-201	OVERALL SITE PLAN	x	
L-202	ARRIVAL SITE PLAN	x	
L-203	POOL SITE PLAN	x	
L-204	HARDSCAPE PLAN	x	
L-206	ARRIVAL HARDSCAPE PLAN	×	
L-206	POOL HARDSCAPE PLAN	x	
L-207	HARDSCAPE SCHEDULE	X	
L-300	SECTIONS	x	
L-301	SECTIONS	x	
L-302	SECTIONS	×	
L-600	CANOPY PLANTING PLAN	×	
L-501	ARRIVAL CANOPY PLAN	×	
L-502	POOL CANOPY PLAN	x	
L-503	UNDERSTORY PLAN	×	
L-504	ARRIVAL UNDERSTORY PLAN	×	
L-505	POOL UNDERSTORY PLAN	x	
L-506	PLANT BOARD	x	
L-507	PLANT BOARD	X	

enea garden design

SEAL:

FOR THE FIRM:
GERARDO JANUER DELGADO
RLA 0001574 DATE: 05.13.21

Al Lamanara Jahap, Januer Laman, durang and entaling
proportion "Book Dackground and Lamanara Jahap
proportion" Book Dackground and Lamanara Januer Lamanara
Lamanara Januer Lamanara
Lamanara Januer Lamanara
Lamanara Januer Lamanara
Lam

No: DATE: ISSUED FOR: 1 05.13.2021 ARB

ISSUED FOR:

ARCHITECTURAL **REVIEW BOARD**

PROJECT No: MA20112 DRAWN BY: AMA, CAL, VDE REVIEWED BY: BHA DATE: 05.13.2021

COVER SHEET

L-000

MAJESTIC TOWER

PREVIOUSLY APPROVED BY ARB (MMPA PROJECT # 00-1101-0100) **APPROVAL DATE 07.01.2021** LONO DATED 04-07-2022

































MAJESTIC TOWER

Bal Harbour, Florida

9601 COLLINS AVENUE BAL HARBOUR, FLORIDA 33154

enea garden design

FOR THE FIRM: GERARDO JAVIER DELGADO R.L.A. 0001574 DATE: 05.13.21

ARCHITECTURAL REVIEW BOARD

PROJECT No: MA20112
DRAWN BY: AMA, CAL, VDE
REVIEWED BY: BHA
DATE: 05.13.2021

DRAWING TITLE: SITE PHOTOS

L-001







			ISPOSITION	_			a au m ma	CANOPYTO	NOTES
REE #	COMMON NAME	BOTANICAL NAME	DBH (in)**	HEIGHT (ft)	SPREAD (ft)	DISPOSITION	CONDITION **	MITIGATE	
83	Seagrape Coconut Palm	Coccoloba uvifera Cocos nucifera	10	30	10	OUTSIDE LIMITS OF WORK OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
85	Coconut Palm	Cocas nucifera	9	30	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nuojfera	9	28	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
87	Coconut Palm	Cocos nucifera	11	28	14	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Sabal Palm Sabal Palm	Sabal Palmetta Sabal Palmetta	10	10 15	8	OUTSIDE LIMITS OF WORK OUTSIDE LIMITS OF WORK	12	0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
	Sabal Palm	Sabal Palmetto	10	14	8	OUTSIDE LIMITS OF WORK	••	0	NOT INCLUDED IN ARBORIST REPORT**
91	Coconut Palm	Cocos nuclera	8	22	14	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
92	Coconut Palm	Cocos nuofera	9	32	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT™
	Coconut Palm	Cocos nucífera	9	18	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nucifera	6 7	17	14	OUTSIDE LIMITS OF WORK OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm Coconut Palm	Cocos nuofera Cocos nuofera	6	28	16	OUTSIDE LIMITS OF WORK	11	0	NOT INCLUDED IN ARBORIST REPORT**
97	Seagrape	Coccoloba uvifera	12	13	15	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
98	Seagrape	Coccolobo uvifera	12	12	12	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
99	Seagrape	Coccoloba uwlfera	- 6	15	10	OUTSIDE LIMITS OF WORK		0	NOT INCLUDED IN ARBORIST REPORT**
100	Seagrape Seagrape	Coccoloba uvljera Coccoloba uvljera	23 11	16 17	15 16	OUTSIDE LIMITS OF WORK OUTSIDE LIMITS OF WORK		0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
102	Seagrape Seagrape	Coccoloba uwljera	16	16	20	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
103	Coconut Palm	Cocos nuajtera	10	28	15	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
104	Coconut Palm	Cocos nuofera	9	28	16	OUTSIDE LIMITS OF WORK	••	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nucifera	9	30	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm Coconut Palm	Cocos nuofera Cocos nuofera	9	32 40	15	OUTSIDE LIMITS OF WORK OUTSIDE LIMITS OF WORK		0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocas nuajera	9	28	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
109	Coconut Palm	Cocos nuojfera	8	20	14	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocas nuajera	9	22	14	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nuojera	10	34 20	16 14	OUTSIDE LIMITS OF WORK OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
114	Coconut Palm Buccaneer Palm	Cocas nuajera Pseudophaenix sargentii	8	5	4	OUTSIDE LIMITS OF WORK	••	0	NOT INCLUDED IN ARBORIST REPORT**
115	Buccaneer Palm	Pseudophoenix sargentii	8	3	4	OUTSIDE LIMITS OF WORK	11	0	NOT INCLUDED IN ARBORIST REPORT**
135	Coconut Palm	Cocos nucifera	9	34	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nuofera	9	22	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
137	Coconut Palm	Coccoloba uvljera	9	28 14	16	OUTSIDE LIMITS OF WORK OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
130	Seagrape Seagrape	Coccolotia uwijera	15	14	15	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
140	Buccaneer Palm	Pseudophoenix sargentii	- 6	5	4	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Buccaneer Palm	Pseudophaenix sargentii	7	5	4	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nucifera	9	37	16	OUTSIDE LIMITS OF WORK		0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nuo)tera	9	26 26	14	OUTSIDE LIMITS OF WORK		0	NOT INCLUDED IN ARBORIST REPORT***
145	Coconut Palm Coconut Palm	Cocos nuafera Cocos nuafera	8 9	28	14 15	OUTSIDE LIMITS OF WORK OUTSIDE LIMITS OF WORK		0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocas nuofera	10	24	14	OUISIDE LIMITS OF WORK	••	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nucifera	9	25	14	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocas nuațera	10	25	14	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
149	Coconut Palm	Cocos nuofera	9	24	14	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
150	Coconut Palm Coconut Palm	Cocos nucifera Cocos nucifera	9	24 28	16 16	OUTSIDE LIMITS OF WORK OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocas nuajera	9	28	16	OUTSIDE LIMITS OF WORK		0	NOT INCLUDED IN ARRORIST REPORT
	Coconut Palm	Cocos nucifera	10	32	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nualfera	9	30	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT™
	Coconut Palm	Cocos nucifera	9	32 34	16 16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm Coconut Palm	Cocas nualfera Cocas nualfera	9	30	16	OUTSIDE LIMITS OF WORK OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocas nucljera	9	30	15	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
159	Coconut Palm	Cocos nucifera	9	34	16	OUTSIDE LIMITS OF WORK	••	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nucifera	9	37	18	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nuafera	10	37	18	OUTSIDE LIMITS OF WORK		0	NOT INCLUDED IN ARBORIST REPORT**
	Washingtonia Palm Washingtonia Palm	Washingtonia filifera Washingtonia filifera	10	13	18	REMAIN RELOCATED	GOOD	0	
492	Coconut Pulm	Cocos nucifera	10	30	26	RELOCATED	MODERATE	0	
493	Washingtonia Palm	Washingtonia filifera	10	12	18	REMAIN	GOOD	0	
	Washingtonia Palm	Washingtonia filifera	19	13	27	RELOCATED	GOOD	0	
	Washingtonia Palm	Washingtonia filifera	8	18	12 26	REMOVE	MODERATE	113	NOT INCLUDED IN ARBORIST REPORT**
497	Coconut Palm Washingtonia Palm	Cocos nucifera Washingtonia filifera	10	30 6	10	REMOVE	MODERATE	79	NOT INCLUDED IN ARRORIST REPORT**
	Washingtonia Palm	Washingtonia filifera	10	6	10	REMAIN	6000	0	SURVEYOR SPEC. INFORMATION*
	Washingtonia Pulm	Washingtonia filfera	12	10	12	RELOCATED	GOOD	0	SURVEYOR SPEC. INFORMATION*
500	Washingtonia Palm	Washingtonia filifero	8	7	15	REMAIN	6000	0	
561	Senegal Date Falm Pygmy Date Palm	Phoenix dactylfero Phoenix roebelenii	39	20 6	36 10	REMAIN REMOVE	MODERATE GOOD	79	
563	Pygmy Date Palm	Phoenix roebelenii	4	5	8	REMOVE	GOOD	50	
561	Pygmy Date Palm	Phoenix roebelenii	3	5	6	REMOVE	GOOD	28	
565	Paurotis Palm (Cluster)	Acnelorrhaphe wrightii	20	23	26	REMOVE	POOR	531	
566	Senegal Date Palm	Phoenix reclinata Phoenix roebelenii	6	20 S	3/1 16	REMAIN	MODERATE	201	
567	Pygmy Date Palm (Triple) Pygmy Date Palm (Triple)	Phoenia roebelenii Phoenia roebelenii	4	5	15	REMOVE	GOOD	113	
569	Pygmy Date Palm	Phoenix roebelenii	3	6	5	REMOVE	MODERATE	20	
570	Christmas Palm	Adonidia merriki	5	11	12	REMOVE	GOOD	113	
	Christmas Palm	Adonidia merrilii	7	12	12	REMOVE	GOOD	113	
	Christmas Palm Date Palm	Adonidia merriki	5 21	11 30	12 30	REMOVE	G000 G000	113	
	Date Palm Date Palm	Phoenix dactylfero Phoenix dactylfero	21	30	30	REMAIN	G000	0	
575	Date Palm	Phoenix dactylifero	20	34	30	REMAIN	G000	0	
579	Date Palm	Phoenix dactylfera	21	35	28	REMAIN	G000	0	
	Date Palm	Phoenix dactyWero	21	35	28	REMAIN	G000	0	
	Date Palm	Phoenix doctylfero	20	32	28	REMAIN	6000	0	
	Date Palm Date Palm	Phoenix dactylifero Phoenix dactylifero	17 18	20 24	28	REMAIN	GOOD DEAD	0	
	Pygmy Date Palm	Phoenis roebelenii	3	6	9	REMOVE	GOOD	64	
	Washingtonia Palm	Washingtonia filifera	10	6	16	RELOCATED	6000	0	
613	Coconut Palm	Cocos nucifera	10	35	34	REMAIN	MODERATE	0	
614	Bamboo	Вотьига грр.	84	20		REMOVE	G000	0	
615	Pygmy Date Palm (4)	Phoenix roebelenii	2, 3, 5, 5	10	12	REMOVE	**	113	NOT INCLUDED IN ARBORIST REPORT**
	Washingtonia Palm	Washingtonia filifera	12	5	10	REMOVE	12	79	NOT INCLUDED IN ARBORIST REPORT**

REE #	COMMON NAME	BOTANICAL NAME		HEIGHT (ft)	SPREAD (ft)	DISPOSITION	CONDITION **	CANOPY TO MITIGATE	NOTES
519		Cocos nucifera	10	30	26	RELOCATED	MODERATE	0	
620	Washingtonia Palm	Washingtonia filifera Washingtonia filifera	10	13	16 10	REMAIN REMAIN	GOOD	0	SURVEYOR SPEC, INFORMATION*
522	Washingtonia Palm Washingtonia Palm	Washingtonio filifera	8	5	14	REMAIN	GOOD	0	SORVETOR SPEC. INFORMATION
	Washingtonia Palm	Washingtonio fillera	8	5	14	REMAIN	GOOD	0	
	Washingtonia Palm	Washingtonia filifera	8	22	16	REMAIN	GOOD	0	
625	Washingtonia Palm	Washingtonio filifera	8	22	16	REMOVE	44	201	NOT INCLUDED IN ARBORIST REPORT**
525	Washingtonia Palm	Washingtonio filifera	8	14	16	REMAIN	GOOD	0	
532	Washingtonia Palm	Washingtonia filifera	8	18	18	REMAIN	GOOD	0	
633	Washingtonia Palm	Washingtonia filifera	0	2	14	REMAIN	GOOD	0	
634	Washingtonia Palm	Washingtonio filifera	8	13	16	REMAIN	GOOD	0	
835	Washingtonia Palm	Washingtonio fil/fera	8	14	18	REMAIN	GOOD	0	
	Washingtonia Palm	Washingtonia filifera	7	13	16	REMAIN	GOOD	0	
	Royal Palm	Roystonea regia	11	5	20	REMOVE	GOOD	314	
	Coconut Palm	Cocos nucifera	10	36	34	REMAIN	MODERATE	0	
539	Coconut Palm	Cocos nucifera	- 8	25	30	REMAIN	MODERATE	0	
640	Pygmy Date Palm	Phoenix roebelenii	- 4	7	6 7	REMOVE REMOVE	GOOD	28 38	
542	Pygmy Date Palm Pygmy Date Palm	Phoenix roebelenii Phoenix roebelenii	4	7	8	REMOVE	GOOD	50	
	Pygmy Date Palm Pygmy Date Palm	Phoenix roebelenii	4	6	8	REMOVE	SOOD	50	
	Pygmy Date Palm	Phoenix roebelenii	4	6	10	REMOVE	GOOD	79	
645	Pygmy Date Palm	Phoenix roebelenii	4	7	8	REMOVE	GOOD	50	
	Pygmy Date Palm	Phoenix raebelenii	5	6	8	REMOVE	GOOD	50	
	Silver Trumpet Tree	Tabebuia caraiba	5	12	12	REMAIN	MODERATE	0	
647a	Silver Trumpet Tree	Tobebulo carolba	17	18	28	REMAIN	MODERATE	0	
548	Pygmy Date Palm (4)	Phoenix roebelenii	12	8	14	REMOVE	GOOD	154	
649	Pygmy Date Palm (Double)	Phoenix roebelenii	7	7	12	REMOVE	GOOD	113	
650	Washingtonia Palm	Washingtonia filifera	10	8	18	RELOCATED	GOOD	0	
651	Washingtonia Palm	Washingtonio filifera	16	9	22	RELOCATED	GOOD	0	
652	Washingtonia Palm	Washingtonio filifera	9	17	12	REMOVE	**	113	NOT INCLUDED IN ARBORIST REPORT**
	Silver Trumpet Tree	Тарериія сагаіра	8	18	20	RELOCATED	MODERATE	0	
654	Washingtonia Palm	Washingtonia filifera	10	3	5	REMOVE	**	20	NOT INCLUDED IN ARBORIST REPORT**
655	Washingtonia Palm	Washingtonio filifera	10	5	8	RELOCATED	GOOD	0	SURVEYOR SPEC. INFORMATION*
856	Silver Trumpet Tree	Tobebuio carosba	14	18	78	REMAIN	MODERATE	0	
	Washingtonia Palm	Washingtonio filifera	10	3	8	REMOVE	**	50	NOT INCLUDED IN ARBORIST REPORT**
658 659	Washingtonia Palm	Washingtonia filifera	12	12	10	REMOVE	**	79	NOT INCLUDED IN ARBORIST REPORT**
	Silver Trumpet Tree	Tobebuio caraiba	10	12	10	REMOVE RELOCATED	SOOD	79	NOT INCLUDED IN ARBORIST REPORT** SURVEYOR SPEC, INFORMATION*
560	Washingtonia Palm	Washingtonia filifera	10	26	12	REMOVE	GOOD	113	NOT INCLUDED IN ARBORIST REPORT**
961	Washingtonia Palm Washingtonia Palm	Washingtonio filifera Washingtonio filifera	10	4	8	REMOVE	44	50	NOT INCLUDED IN ARBORIST REPORT**
							POOR	50	NOT INCLUDED IN ARBURST REPORT
664	Silver Trumpet Tree Washingtonia Palm	Tabebuia caraiba Washingtonia filifera	9	14	8 18	REMOVE RELOCATED	GOOD	0	
	Date Palm	Phoenix doctylifera	18	28	26	REMAIN	GOOD	0	
568	Washingtonia Palm	Washingtonia filifera	8	15	12	REMOVE	**	113	NOT INCLUDED IN ARBORIST REPORT**
000	Washingtonia Palm	Washingtonia filifera	14	10	24	REMOVE	GOOD	452	NOT INCODED IN ARBONIST REPORT
	Washingtonia Palm	Washingtonio filifera	15	12	24	RELOCATED	GOOD	0	
571	Silver Trumpet Tree	Tobebulo carolba	8	14	15	RELOCATED	MODERATE	0	
	Washingtonia Palm	Washingtonia filifera	8	9	18	RELOCATED	GOOD	0	
	Washingtonia Palm	Washingtonia filifera	10	8	8	REMOVE	GOOD	50	SURVEYOR SPEC, INFORMATION*
	Washingtonia Palm	Washingtonio filfera	8	12.	16	RELOCATED	MODERATE	0	
	Washingtonia Palm	Washingtonio fillera	9	12	18	RELOCATED	GOOD	0	
676	Washingtonia Palm	Washingtonio filifera	10	3	5	REMOVE	44	20	NOT INCLUDED IN ARBORIST REPORT**
577	Washingtonia Palm	Washingtonio filifera	8	8	16	RELOCATED	GOOD	0	
678	Washingtonia Palm	Washingtonia filifora	9	18	20	RELOCATED	GOOD	0	
679	Washingtonia Palm	Washingtonia filifera	9	5	18	RELOCATED	GOOD	0	
680	Washingtonia Palm	Washingtonio filifera	9	13	20	RELOCATED	GOOD	0	
581	Pygmy Date Palm (Double)	Phoenix roebelenii	8	7	15	REMOVE	GOOD	177	
682	Washingtonia Palm	Washingtonia filifora	9	15	17	RELOCATED	GOOD	0	
683	Washingtonia Palm	Washingtonia filifera	9	12	18	RELOCATED	GOOD	0	
	Pygmy Date Palm (4)	Phoenix roebelenii	8	7	16	REMOVE	GOOD	201	
	Washingtonia Palm	Washingtonio filifera	10	6	5	REMOVE	GOOD	20	SURVEYOR SPEC. INFORMATION*
	Washingtonia Palm	Washingtonia filifera	10	10	10	REMOVE	GOOD	79	SURVEYOR SPEC. INFORMATION*
687	Washingtonia Palm	Washingtonio filifera	10	12	18	RELOCATED	GOOD	0	
	Pygmy Date Palm (Triple)	Phoenix roebelenii Phoenix roebelenii	8	2	5	REMOVE	SOOD	113	
691	Pygmy Date Palm Washingtonia Palm	Phoenix roebelenii Washingtonio filifera	8	6	18	REMOVE	GOOD	0	
692	Washingtonia Palm	Washingtonio filifera	8	12	18	RELOCATED	GOOD	0	
	Washingtonia Palm	Washingtonia filifora	0	1	8	REMOVE	GOOD	50	
994	Date Palm	Phoenix dactylifera	20	25	30	REMAIN	MODERATE	0	
	Date Palm	Phoenix dactylifera	20	24	28	REMAIN	MODERATE	0	
	Date Palm	Phoenix dactylifera	18	25	28	REMAIN	MODERATE	0	
	Date Palm	Phoenix dactylifera	18	28	28	REMAIN	MODERATE	0	
996	Date Palm	Phoenix dactylifera	18	25	28	REMAIN	MODERATE	0	
699	Date Palm	Phoenix dactylifera	18	30	30	REMAIN	GOOD	0	
700	Date Palm	Phoenix dactylifera	18	28	28	REMAIN	MODERATE	0	
701	Date Palm	Phoenix dactylifera	18	28	28	REMAIN	GOOD	0	
	Date Palm	Phoenix dacty/Jera	18	28	28	REMAIN	GOOD	0	
703	Date Palm	Phoenix dactylifera	18	28	28	REMAIN	MODERATE	0	
704	Date Palm	Phoenix d'actylifera	18	28	28	REMAIN	MODERATE	0	
	Date Palm	Phoenix doctylifera	18	25	16	REMAIN	MODERATE	0	
706	Date Palm	Phoenix dactylifera	19	26	20	REMAIN	MODERATE	.0	
707	Date Palm	Phoenix dactylifera	20	26	26	REMAIN	MODERATE	0	
708	Pygmy Date Palm (Triple)	Phoenix roebelenii	15	6	10	REMUVE	GOOD	201	
709	Pygmy Date Palm (Double)	Phoenix roebelenii	0	3	9	REMOVE	MODERATE	54	
	Pygmy Date Palm (Triple)		8	- 6	PRE	VIOUSE	V APP	HOV	ED BY ARB
711	Pygmy Date Palm (Double)	Phoenix roebelenii	8	5	- 11	NEMOVE DEMOVE	9000	- 115	
712	Pygmy Date Palm (Triple)	Phoenix roebelenii	10	6	CDAR	IDA DPC	TENT.	#201	0-1101-010
713	Senegal Date Palm	Phoenix realinata		18	CIAILA	ALL MARKET	NO.	7753	
714	Silver Trumpet Tree	Tobebuia caraiba	15	18	16	REMAIN	MODERATE	0	1.2021
715	Silver Trumpet Tree	Tobebulo carolba	8	16	APP	HOVAL	DATE	07.0	1.2021
716	Silver Trumpet Tree	Tobebuio caraiba	16	22	28				
	Silver Trumpet Tree	Tobebuia caraiba	7	16	LON	IO DATE	DMOA.	07-5	2022
	Bismarck Palm	Bismarckia nobilis	11	18	-70-1		3000	- 51 -	
723	Coconut Palm	Cocos nuclfera	9	18	16	GUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
	Coconut Palm	Cocos nucifera	9	20	14	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
725		Cocos nucifera	9	18	14	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**
726	Coconut Palm	Cocos nucifera	9	18	16	OUTSIDE LIMITS OF WORK		0	NOT INCLUDED IN ARBORIST REPORT** NOT INCLUDED IN ARBORIST REPORT**
			8	18	16	GUTSIDE LIMITS OF WORK		0	
727	Coconut Palm Coconut Palm	Cocos nucifera Cocos nucifera	8	18	16	OUTSIDE LIMITS OF WORK	**	0	NOT INCLUDED IN ARBORIST REPORT**

MAJESTIC TOWER

Bal Harbour, Florida

9601 COLLINS AVENUE BAL HARBOUR, FLORIDA 33154

enea garden design

FOR THE FIRM:
GERARDO JAVIER DELGADO
R.L.A. (20015191 DATE: 05.13.21

All artitudes occipius ginne concepts consispend structures to take to begin to the concepts consispend structures to be concepts to take to begin to the concepts occipies to take to begin to the concepts occipies to take to begin to the concept occipies to occident to occupie to o

No: DATE: ISSUED FOR: 1 05:13:2021 ARB

ARCHITECTURAL REVIEW BOARD


PROJECT No: MA20112 DRAWN BY: AMA, CAL., VDE REVIEWED BY: BHA DATE: 05.13.2021

DRAWING TITLE:

TREE DISPOSITION PLAN

L-101





NOTES:

1. A 'Y' EMPTY TABIN THE DBH COLUMN DENCITES NO TRUCK AT 4.5 FEET ABOVE GRADE.

2. TREES LESS THAN 12' IN HEIGHT AND 2'' DBH AND PALMS LESS THAN 16' IN HEIGHT AND 2''
DBH AREN ON' REQUIATED HUGHE IN 17 NOD DO NOT REQUIRE MITIGATION ALL

3. FLANTS PROMERTED BY THE CITY OF BAL HARBOUR SHALL BE REMOVED FROM ALL

3. FLANTS PROMERTED BY THE CITY OF BAL HARBOUR SHALL BE REMOVED FROM ALL

3. FLANTS PROMERTED BY THE CITY OF BAL HARBOUR SHALL BE REMOVED FROM ALL

4. TREE DEPOSITION PLAN AND SCHEDULE PER TREE SURVEY AND CORRESPONDING AMPORTS HEROLD TO AND SCHEDULE PER TREE SURVEY AND CORRESPONDING AMPORTS HEROLD TO AND AND SCHEDULE PER TREE SURVEY AND CORRESPONDING

- DBH, HEIGHT AND SPREAD SPECIFICATIONS REFERENCE TO VEGETATION SURVEY SPECIFICATIONS.
- SPECIFICATIONS.

 SPECIMEN NOT INCLUDED IN ARBORIST REPORT, ANY SPECIFICATIONS REFERENCE VEGETATION SURVEY SPECIFICATIONS.

CATEGORY	BOTANICAL NAME	COMMON NAME	QUANTITY	VALUE	TOTAL
SHADE 1	Clusia rosea	Autograph Tree	4	500	2000
SHADE 1	Coccoloba uvifera	Sea Grape	10	500	5000
SHADE 1	Delonix regio	Royal Poinciana	3	500	1500
SHADE 1	Clophyllum ontillanum	Brazilian Beauty Leaf	2	500	1000
SHADE 1	Tabebula caralba	Silver Trumpet	4	500	2000
PALM 1	Cocos nucifero	Coconut Palm	13	300	3900
PALM 1	Phoenix dacty#Jera	Date Palm	1	300	300
PAIM 1	Phoenic reclinata	Senegal Date Palm	1	300	300
TOTAL PROV	IDED CANOPY				16000
TOTAL PROV	IDED SPECIES				8

LANDSCAPE LEGEND Zoning District: OF Net Lot Area: 3 acres 130,810 square feet

	REQUIRED	PROVIDE
A. Square feet of open space required by Chapter 33, as indicated on site plan: Net lot area = 130.810 square feet x 25 % = 32.702 square feet	32,702	22,565
B. Square feet of parking lot open space required by Chapter 18A, as indicated on site plan: The number of parking spaces N/A x 10 square feet per parking space =	N/A	N/A
C. Total square feet of landscaped open space required by Chapter 33 = A + B =	32,702	22,565

TREES		
A. The number of trees required per net lot acre	28	
less the existing number of trees that meet minimum requirements (minus) 8	TREES,	55 PALMS
= 0 trees x net lot acreage =	D	
B. 30% palm trees allowed (two palms = one tree) Palms provided =	D	15 (7 TO COU
C. Percentage of native trees required = the number of trees provided x 30% =	0	20
D. Street trees (max. average spacing of 35' o.c.): N/A linear feet along street + 35 =	N/A	N/A
Palms as street trees (max. average spacing 25' o.c.): 646 linear feet along street + 25 =	26	19
Street trees located directly beneath power lines (maximum average spacing of 25' o.e.): N/A linear feet along street + 25 =	N/A	N/A
F. Total number of trees provided	26	42

enea

MAJESTIC TOWER

Bal Harbour, Florida


FOR THE FIRM:

GERARDO JAVIER DELGADO
R.L.A. 0001574 DATE: 05.13.21

REVIEW BOARD PROJECT No: MA20112 DRAWN BY: AMA, CAL, VDE

TREE DISPOSITION PLAN

L-102 MAJESTIC TOWER




Sheet L-201






Sheet L-202






Sheet L-203






Sheet L-204






Sheet L-205





Sheet L-206





-		HARDSCAPE SCHEDULE	
SYTM	MATERIAL	DESCRIPTION	LOCATION
la la	COBBLE PAVER (VEHICULAR)	MATERIAL: WHITE STONE FINISH: FLAMMED SIZE: 4"x4"x2" THICK	DRIVEWAY BANDING; DRIVEWAY
16	COBBLE PAVER (VEHICULAR)	MATERIAL: LIGHT GRAY STONE FINISH: FLAMMED SIZE: 4"x4"x2" THICK	DRIVEWAY
1c	COBBLE PAVER (VEHICULAR)	MATERIAL: GRAY STONE FINISH: FLAMMED SIZE: 4"x4"x2" THICK	DRIVEWAY
2a	PEDESTRIAN PAVER	MATERIAL: LIGHT GRAY MARBLE SERIES: MONTEREY PAVERS FINISH: SANDBLASTED SUE: 18"x36"	ENTRY
2b	POOL DECK PAVING	MATERIAL: LIGHT GRAY MARBLE SERIES: MONTEREY PAVER FINISH: SANDBLASTED SIZE: 18*x36"	POOL DECK PAVER
3	WOOD DECK	MATERIAL: IPE SIZE: 6" x 1" STAGGERED FINISH: NATURAL	RESTAURANT OUTDOOR DINING
4	LANDSCAPE EDGING	MATERIAL: COL-MET 1011BK SIZE: 120'L x 5'W COLOR: BLACK CUT: 1/4" GA THICKNESS	PLANTING BEDS
5	STUCCO FINISH	MATERIAL: STUCCO FINISH: SMOOTH, PAINTED COLOR: WHITE TO MATCH EXISTING BUILDING STUCCO	ENTRY DRIVE; PARK
6	WALL VENEER	MATERIAL: MARBLE SERIES: MONTEREY PAVERS FINISH: SANDBLASTED SIZE: 18*x36" X 5/8"	DRIVEWAY DROP-OFF CENTRAL PLANTER
P1	WATERLINE TILE	MATERIAL: GLASS TILE COLDR: LIGHT GREY FINISH: GLOSSY SIZE: 2" X4"	POOL + SPA
P2	POOL HNISH	MANUFACTURER: PEBBLE SHEEN COLOR: ARCTIC WHITE	POOL + SPA
P3	NOSING + SWIN LANE TILE	MATERIAL: GLASS TILE COLOR: PERMANENT BLACK FINISH: CORUNDUM SIZE: 2" X 2"	POOL + SPA
8	PEDESTRIAN GATE/FENCE	MATERIAL: IPE / 316 ST. STEEL IPE FINISH: NATURAL METAL COLOR: WHITE	BEACH GATE
9	GUARDRAIL TYPE 1	MATERIAL: IPE / 316 ST. STEEL IPE FINISH: NATURAL METAL COLOR: WHITE	PARK
94	GUARDRAIL TYPE 2	MATERIAL: IPE / 316 ST. STEEL / GLASS IPE FINISH: NATURAL METAL COLOR: WHITE	PARK
10	TRELUS	MATERIAL: IPE / 316 ST. STEEL IPE FINISH: NATURAL METAL COLOR: WHITE	
11	PERGOLA	MATERIAL: IPE / 316 ST. STEEL IPE FINISH: NATURAL MILIAL COLOR: WHITE	
12	SST. CABLE	MATERIAL: STAINLESS STEEL MODEL: INOX LINE RECTANGLE SYSTEM	ENTRY; POOL DECK
13	ROOT BARRIER	MODEL: UB 36 SIZE: 36" HT	
14	PEBBLES	MATERIAL: ROUNDED PEBBLES SIZE: 1"-2" COLOR: BLACK	ENTRY WATER GARDEN / POO

MAJESTIC TOWER

Bal Harbour, Florida

9601 COLLINS AVENUE BAL HARBOUR, FLORIDA 33154

enea garden design

SEAL:

FOR THE FIRM:
GERARDO JANUER DELGADO
R.L.A. COOLEGA DO ATE: 05.13.21
If there are a first of the coolega delay of

No: DATE: ISSUED FOR: 1 05.13.2021 ARB

ARCHITECTURAL REVIEW BOARD

PROJECT No: MA20112 DRAWN BY: AMA, CAL, VDE REVIEWED BY: BHA DATE: 05.13.2021

DRAWING TITLE: HARDSCAPE SCHEDULE SHEET NO:

L-207





PREVIOUSLY APPROVED BY ARB (MMPA PROJECT # 00-1101-0100) **APPROVAL DATE 07.01.2021** LONO DATED 04-07-2022



L-300







Sheet L-500






Sheet L-501





Sheet L-502






Sheet L-503





Sheet L-504






Sheet L-505











MAJESTIC TOWER

Bal Harbour, Florida

9601 COLLINS AVENUE BAL HARBOUR, FLORIDA 33154

enea garden design

FOR THE FIRM:
GERARDO JAVIER DELGADO
R.L.A. 0001674 DATE: 05.13.21

All withous going in given increases consign and remember there is a sign of one overriding the control of the

No: DATE: ISSUED FOR: 1 05.13.2021 ARB

ARCHITECTURAL REVIEW BOARD

PROJECT No: MA20112 DRAWN BY: AMA, CAL, VDE REVIEWED BY: BHA DATE: 05.13.2021

DRAWING TITLE: PLANT BOARD

L-507



- VILLAGE -

The undersigned Agent/Owner request(s) Architectural Review Board review of the following application(s):

□ New Building (\$2,500.00)	□Alteration/ Additions (\$1,000.00)	Revision (\$250.0	0)	
	ARB202A-00	11	(Levision	to ARB-21-05	5001
PROJECT INFORMATION					
Street Address of the Subje	ct Property: 9601 Col	lins A	٤		-
	1A Jestic Tower				
	E SUB PB44-27, L				
Block(s) 13 4465 50.	ft. M/L Section(s)	OCEAN Fr	ont section	n of Bal Harbo	20/
Folio No. 12 - 222	6-038-001				
Owner(s): MAJESH	C TOWER COMMUN	ity Ass	ociation	INC	-
Mailing Address: 960	1 Collins AVE	·			_
Telephone: 305 - 8	364-0122	Fax			
Other		Email_ M	DURGES	@MAJestiz to	ver, lo
LAND SAPE Architect(s)/Engineer(s):	KEN GARDNER				-
Architect(s)/Engineer(s) Mai	iling Address: 17670 N	W 78th AV	E # 214 P	MAMI, FL 3300	5
Telephone: Business _	305-392-1016	Fax			_
Other		Email_ KO) & GSLADESH	e com	_
PROJECT INFORMATION					
Project Description(s):	NOSCAPE renovation	n to keel	DREA HOU	VELLAS PLANT	ings
HADGGADE AND C	Abana Frants			1	
Had Scape and C Estimated project cost*:	1.ZMILIAN				-01
(*Estimated cost shall be +.	7-10% of actual cost) al(s) and Action(s):	0-4-	7-2022		



NOTE: BOTH SIGNATURES OR AFFIRMATION/CONSENT ARE REQUIRED ::::::::

Owner / Representative Print	ted Name:	Architect(s)/Engineer(s) Print Name:			
JANINE POTH		FEN GARDNER			
Owner / Representative Sign	ature:	Architect(s)/Engineer(s) Sig	gnature:		
ghth		Say Opide			
Address:	BAL BAL	Address:	MIAMI, Ft		
960/ Collins Ave.	JULY 1902, HWY0017	17670 NW 78 THAV	15 214 33015		
Telephone: Fax:	Email: PER POTHDALE. 4	Telephone: Fax:	Email:		
305 7786914	JANINIC.	305-392-1016	KENDGLADESLAD. COM		
•		Architect/Engineer Seal:	~~~~		
		0	ANDSCADE		
		4	ERIC		
		1	The Saliet		
		SISIN	LA 0001569 Z III		
		A A A A A A A A A A A A A A A A A A A	STATE STATE		
		8:	OF *		
		A.	FLORIDA		
NOTARIZATION		NOTARIZATION	Comment of the Commen		
STATE OF FLORIDA		STATE OF FLORIDA			
COUNTY OF MIAMI-DADE		COUNTY OF MIAMI-DADE			
Sworn to or affirm and subscr	ibed before me	Sworn to or affirm and sub	scribed before me		
this St day of APRIC	, in the year 20 <u>2</u> 9	this 5th day of Arriv	, in the year 20 24		
by Panine poth	who has taken an	by KEN GAMOURI			
oath and is personally known as identification.	to me or has produced_	an oath and is personally k produced_as identification.			
		produces_as rasminsation.			
My Commission Expires:		My Commission Expires: _			
		0.1			
sadu 4 ps	3	Chan	\mathcal{O}_{-}		
Notary Public		Notary Public			
- SARY PUBL	CAROLINA I. CRUZ		RISTOPHER GARCIA MMISSION # HH 104555		
	commission # HH 095955 xpires February 22, 2025	EXF	PIRES: March 21, 2025		
A THE CANADA	nded Thru Budget Notary Services	Bonded T	hru Notary Public Underwriters		



And the second of the second o

e de Stary e de Stary de Selvino

CHRISTOPHEN GARCIA
LIV COMMUSSION 2 HA 10:1556
EXPIRES, March 21, 2023
Bordad Tra Holdy Pulss influences








PROFESSIONAL PREPARER'S STATEMENT OF LANDSCAPING COMPLIANCE

PROCESS NUMBER
Legal description: Lot, Block, Subdivision P.B Page, Development name MAJESTIC TOWER - POOL AFFA Located at (address) 960 CHINS AND, LANTIARCOR, FL
I/We hereby certify that the landscaping/irrigation plan being submitted for the above captioned complies with the requirements of Ordinance 98-13 (landscaping ordinance) as to species, height, trunk width and location at time of planting, and that the species as shown are in accordance with the accepted species approved by Miami-Dade County and that none of the species are from the prohibited list.
Additionally automatic sprinkler system (if applicable) comply with requirement of said ordinance as to type of heads, spray system, location, etc.
I/We further certify that I/we am/are authorized under Chapter 481, Florida statutes to prepare and submit this landscaping/irrigation plan. Comparison Chapter Seal: (If Contourion) ERIC Contourion Contourion ERIC Contourion ERIC Contourion ERIC Contourion Contour
Witness my signature and official seal this 5th day of April 20024, in the County and State aforesaid, the date and year last aforesaid.
Notary Public
CHRISTOPHER COARLIA Print Name

My Commission Expires:





April 7, 2022

Florida Department of Environmental Protection (FDEP)
Coastal Construction Control Line (CCCL) Program
Division of Water Resource Management
2600 Blair Stone Road, Mail Station 3522
Tallahassee, Florida 32399-2400
Attn: Ms. Celora Jackson - Engineer

RE:

Letter of No Objection (LONO)

Proposed Majestic Tower Condominium Project

Recreational & Pool Deck / Landscaping / Front Entry Upgrades

9601 Collins Avenue

Bal Harbour Village, Florida 33154 MMPA Project No. 00-1101-0100

Dear Ms. Jackson:


The community of Bal Harbour Village, Florida is aware that the Majestic Towers Condominium is seeking to obtain approval from the Florida Department of Environmental Protection (FDEP) for a CCCL permit related to the above improvement project. The Village's Architectural Review Board (ARB) reviewed / approved these improvements at its July 1, 2021 meeting. Prior to the ARB's action the Village's staff reviewed / signed off on the project ensuring that the Village's collective Land Development Regulations /Zoning Code were complied with (setbacks / open space / other).

In light of the above, Bal Harbour Village has no objections to the proposed improvements. Should you have any questions, please feel free to contact our offices at 305-865-7525.

Sincerely

Eljezer Palacio Building Official

CC: Michael J. Miller, AICP - Consultant Village Planner



Memorandum

Date:

April 5, 2024

To:

Architectural Review Board

From:

GSLA Design Inc.

Reference:

ARB Revised Landscape Application

Project:

MA20112 MAJESTIC TOWER

Project No.:

Copy:

This project exists of a landscape renovation of an existing multi-family condominium.

The existing Pool and Spa are to remain. The pool deck materials will be changed out to light gray stone pavers, the plantings will be replaced and enhanced with new salt and wind tolerant materials. At the building's restaurant the existing outdoor dining space will be enhanced with a pergola and at-grade deck with plantings around it. The existing cabanas will have wood panels applied to the exterior face, and new lighting. The current metal picket pool fence replaced with a wood and stone fence and an enhanced entry structure.

This is a revision to the previously approved landscape plans by ARB in 2021.

This does not represent a materially deviation from the approved plans.

These plans have been revised, because the Condominium association has decided to maintain the Pool and Spa in the exact locations and shapes, just providing new finishes. The Association wanted to simplify the design, and the Landscape Architect has been changed.





Detailed Report

Generated On: 06/17/2024

PROPERTY INFORMATION	
Folio	12-2226-038-0001 (Reference)
Property Address	0 , FL
Owner	REFERENCE ONLY
Mailing Address	
Primary Zone	5000 HOTELS & MOTELS - GENERAL
Primary Land Use	0000 REFERENCE FOLIO
Beds / Baths /Half	0/0/0
Floors	0
Living Units	0
Actual Area	0 Sq.Ft
Living Area	0 Sq.Ft
Adjusted Area	0 Sq.Ft
Lot Size	0 Sq.Ft
Year Built	0

ASSESSMENT INFORMATION			
Year	2023	2022	2021
Land Value	\$0	\$0	\$0
Building Value	\$0	\$0	\$0
Extra Feature Value	\$0	\$0	\$0
Market Value	\$0	\$0	\$0
Assessed Value	\$0	\$0	\$0
DENEETS INCODMATION			

RENEFILI S INFORM	1A I IUN			
Benefit	Type	2023	2022	2021
	enefits are applicable Board, City, Regiona		Values (i.e.	



TAXABLE VALUE INFORMATION			
Year	2023	2022	2021
COUNTY			
Exemption Value	\$0	\$0	\$0
Taxable Value	\$0	\$0	\$0
SCHOOL BOARD			
Exemption Value	\$0	\$0	\$0
Taxable Value	\$0	\$0	\$0
CITY			
Exemption Value	\$0	\$0	\$0
Taxable Value	\$0	\$0	\$0
REGIONAL			
Exemption Value	\$0	\$0	\$0
Taxable Value	\$0	\$0	\$0

The Office of the Property Appraiser is continually editing and updating the tax roll. This website may not reflect the most current information on record. The Property Appraiser and Miami-Dade County assumes no liability, see full disclaimer and User Agreement at





Generated On: 06/17/2024

Property Information

Folio: 12-2226-038-0001 **Property Address:** 0

Roll Year 2023 Land, Building and Extra-Feature Details

LAND INFORMATION					
Land Use	Muni Zone	PA Zone	Unit Type	Units	Calc Value

Generated On: 06/17/2024

Property Information

Folio: 12-2226-038-0001 **Property Address:** 0

Roll Year 2022 Land, Building and Extra-Feature Details

LAND INFORMATION					
Land Use	Muni Zone	PA Zone	Unit Type	Units	Calc Value

Generated On: 06/17/2024

Property Information

Folio: 12-2226-038-0001 **Property Address:** 0

Roll Year 2021 Land, Building and Extra-Feature Details

LAND INFORMATION					
Land Use	Muni Zone	PA Zone	Unit Type	Units	Calc Value

Generated On: 06/17/2024

Property Information

Folio: 12-2226-038-0001 **Property Address:** 0

FULL LEGAL DESCRIPTION
MAJESTIC TOWER AT BAL HARBOUR
CONDO DESC
OCEAN FRONT SEC OF BAY HARBOR
RE SUB PB 44-27
LOT 1
& PORT LYING EAST & ADJANCENT
WEST OF EROSION LINE PER
PB 105-62
LOT SIZE 134465 SQ FT M/L
FAU 12 2226 001 0010

SALES INFORMATION			
Previous Sale	Price	OR Book-Page	Qualification Description



ARCHITECTURAL REVIEW BOARD MEMORANDUM

TO: Architectural Review Board Members

FROM: Eliezer Palacio, Building Director DATE:

7/1/2021

SUBJECT: 9601 Collins Avenue

Landscape renovation of an existing multifamily condominium

BACKGROUND

The Village of Bal Harbour the "Village" received an Architectural Review Board (ARB) application on May 17, 2021 for the Landscape renovation of an existing multifamily condominium located at <u>9601</u> Collins Avenue ("the Property").

The Property sits on Lots 1, Majestic Tower at Bal Harbour and is located in the Ocean Front zoning district of the Bal Harbour Village.

THE PROJECT (AE Description)

The project consists of a landscape renovation of an existing multifamily condominium. Portions of the property (the north podium and east beach area) are outside of the limits of landscape renovation; however, the applicant will add a prefabricated playground structure accessible to residents of the Majestic Tower only on this mezzanine level. For the west portion of the property along Collins Ave, the landscape canopy trees will be selectively thinned to remove trees that are overgrown or in poor condition, and trees will either relocated or replaced to bring a fresh design vision to the property. The understory planting materials will also be replaced with new materials consistent with the character of Bal Harbour and suitable for the conditions of the site.

Both driveways (Collins and 96th) and the residence entrance drop-off will have new paving materials proposed, bringing the palette in harmony with the architectural façade and proposing a similar scallop pattern to the existing driveway while working within the existing conditions of the planter walls.

An opening is proposed in these walls at three locations to be able to provide for pedestrian access to an underutilized portion of the landscape and transform this space into a tranquil garden park.

The pool deck on the east portion of the property will undergo a renovation to change the shape of the pool to a more contemporary shape with clean lines while staying within the existing pool shell's structural footprint. The spa will also be redesigned with the same clean lines while utilizing the existing piles. The pool deck materials will be changed out to a light gray stone paver, the plantings will be replaced and enhanced with new salt and wind tolerant materials. At the building's restaurant, the existing outdoor dining space will be enhanced with a pergola and at-grade deck with plantings around it. The pool deck space is proposed to be unified with a wraparound trellis extension at the existing cabanas, and the current metal picket pool fence replaced with a glass panel fence with greater visibility towards the beach.

It is the opinion of this writer that the proposed new addition to an existing two-story single-family residence follows the Village's Appearance Code and Zoning Ordinance. The Village Planning and Zoning Consultant and the Park's and Public Spaces Department has reviewed the plans and concur that the plans comply.

RECOMMENDATION

I recommend that the Board review the submittal for compliance and if they concur with my recommendation, issue a Certificate of Appropriateness.

If approved, the following conditions should be added to the motion:

- 1. Landscape Architect shall provide certified letter demonstrating compliance with Miami-Dade County Chapter 18A.
- 2. Trees shall be added to meet or exceed the previously approved tree canopy prior to issuance of a Certificate of Occupancy.
- 3. Compliance with Village Code of Ordinances Section 20-29, regarding obstruction of water meters, and Section 21-358 regarding walls, fences and landscape plantings.
- 4. Any new hedge must be planted at least 10' from the edge of the curb (existing hedge may remain).
- 5. Any new trees must be planted at least 10' from the edge of the curb (existing trees/palms may remain).
- 6. A construction contract and or detailed estimate of the proposed improvements is required to be submitted to establish proposed construction value.
- 7. Zoning and Flood Resistant Design Review information included in this approval and backup report consists only of a preliminary review against the basic intent of the Village's zoning code and F.B.C. Chapter 16 requirements. Complete review and compliance with the Village Zoning Code and the F.B.C. shall be required prior to permit approval. An Indemnification and Hold Harmless Agreement for Issuance of a Building Permit regarding FEMA's requirements regarding substantial improvement of single-family residences is required to be executed by the Owner and General Contractor prior to permit issuance.